


GRRIP II Watershed Analysis for Rehoboth, MA

Estimates of Land Use, Impervious Surface and
Annual Nonpoint Source Pollution Loads


2003 Land Use Types	
Crop Land	
Pasture	
Forest	
Non-Forested Wetland	
Mining	
Open Land	
Participation Rec.	
Spectator Rec.	
Water-based Rec.	
Multi-Fun. Rec.	
High Density Res.	
Medium Dens. Res.	
Low Dens. Res.	
Salt Water Wetland	
Commercial	
Industrial	
Urban Open	
Transportation	
Waste Disposal	
Water	
Woody Perennial (Includes Cranberry Bogs and Nurseries)	



- Drainage System
- Potential Vernal Pools
- Certified Vernal Pool
- Public Water Supply
- Public Beach
- Shellfish Beds
- Rarebird_noss
- Rarefish_noss
- Rarecrustacean_noss
- Rarereptile_noss
- Rarebirdive_noss
- Intermittent Wellhead Protect
- Cold Water Fisheries
- Anadromous Fish Run
- Critical Area after Storm Event
- Wetlands
- Solid Waste Facility
- Estimated and Priority Habitats
- ACEC
- Zone 2
- Zone B
- Rivers and Streams
- Lakes & Ponds
- Road Island Towns
- Other MA Towns
- Town Boundary
- Ocean
- Transmission Lines
- Railroad

Road (Mass Hwy Functional Classes)

- Local Rd & Non-Essential Functional Class Rds (F-Off-Rd)
- Interstate (F-1)
- Rural Principal Arterial & Urban Ext (F-2)
- Rural Collector & Urban Minor (F-3)
- Rural Urban Primary & Urban Major (F-4)
- Urban Minor Arterial or Rural Major Collector (F-5)
- Urban Collector or Rural Minor Collector (F-6)



1



2

Route 44, bridge between Danforth and Broad Streets. To the east, a ditch has been cut by storm-water flows around the headwall with erosion and rilling evident. To the west, there is deteriorated concrete flow-attenuators at the terminus of the headwall with evidence of erosion and rilling. The site is located over the Palmer River in a priority habitat area near a small community water supply/wellhead.



3



4



5

Route 44, bridge between Danforth and Broad Streets: east side of Route 44, there is a paved main near the bridge, a paved shoulder, and a paved shoulder through vegetated understory. The paving is in good condition. The headwall on the bridge has fading and cracking concrete. These structures are located adjacent to and over the Palmer River in a priority habitat and near a small community water supply/wellhead.

